



Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



PART L2 and BRE 176 BUILDING THERMOGRAPHIC INSPECTION FOR:

SAMPLE

LOCATION:

ADDRESS 1
ADDRESS 2
ADDRESS 3
ADDRESS 4
POST CODE

DATE

22/04/11

TI JOB NO.

TI_156xx



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Introduction to your Ti Thermal Imaging LTD internal building inspection

Inspection Details	
Survey commissioned by	Sample Construction
Contact Name	-
Purpose of Survey	Part L2 Insulation Continuity Investigation
Reason for survey	Part of specification to check the presence of Rockwall insulation
Survey Inspection Notes	After initial site inspection and briefing with the site supervisor, relevant PPE was utilised. Internal and external surface temperatures were recorded and then external and internal threshold temperatures were calculated and ambient temperatures were also recorded. Images were then captured of all elevations and a green isotherm presents itself at areas of anomalous temperature readings or specifically where the TCso/TCsi has been breached. These images were then processed into Visual Fault Documentation Pages for review. An executive summary has been produced summarising the fault areas with suspected root cause and recommended remedial action.
Property Construction Details	2012 built internal cladding with 180mm side, 240mm roof Rockwool, cavity wall 100mm
Applicable Formulas	YES
Inspection Commencing	05.00
Weather	Dry
Wind Speed	2mph
Ambient Temperature Internal	16°C
Ambient Temperature External	5°C
Temperature Delta between Internal and External	11°C
Inspection Specification	
Camera Make and Model	FLIR ThermaCAM P620
Camera Serial Number	SN404004189
Software	Tablet PC Inspectrend Client Webmanager Enabled
Thermographer	Richard Wallace
Thermographer Certification ID	49595
Survey BS Accordance	BS EN 13187: 1999 Thermal Performance of Buildings
Company Accreditation	ISO 9001-2008 GB2003936
Calibration Date	Feb 2013



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Formulas Explained

Name	Component	Explanation or Formula
fCRsi	Critical Temperature Factor	Given constant outlined in BRE paper IP17/01 and relates to mould growth or surface condensation. Used for assessment of insulation in properties. Residential, office and industrial units use: 0.75 High humidity buildings such as swimming pools use: 0.9
Tsi	Average Internal Surface Temperature	Mean temperature taken from multiple surface temperature readings
Tso	Average External Surface Temperature	Mean temperature taken from multiple surface temperature readings
TCsi	Internal Threshold Temperature	$fCRsi(Tsi-Tso)+Tso$
TCso	External Threshold Temperature	$fCRsi(Tso-Tsi)+Tsi$

Inspection Formula

Critical Temperature Factor	0.75	WAREHOUSE ONLY		
Mean external elevation temperature (Tsi)	Avg	Temp 1	Temp 2	Temp 3
	3.33	3.5	3.2	3.3
Mean Internal elevation temperature (Tso)	Avg	Temp 1	Temp 2	Temp 3
	16.13	15.9	16.2	16.3
TCsi = 0.75*(Tso-Tsi)+Tsi	12.93	(Green Isotherm on thermograms if temperatures found above this level)		
TCso = 0.75*(Tsi-Tso)+Tso	6.53	(Green isotherm on thermograms if temperatures found below this level)		

Critical Temperature Factor	0.75	OFFICE ONLY		
Mean external elevation temperature (Tsi)	Avg	Temp 1	Temp 2	Temp 3
	6.33	6.5	6.2	6.3
Mean Internal elevation temperature (Tso)	Avg	Temp 1	Temp 2	Temp 3
	18.13	17.9	18.2	18.3
TCsi = 0.75*(Tso-Tsi)+Tsi	15.18	(Green Isotherm on thermograms if temperatures found above this level)		
TCso = 0.75*(Tsi-Tso)+Tso	9.28	(Green isotherm on thermograms if temperatures found below this level)		



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Executive and Energy Performance Summary

Table of Thermal Faults found for this inspection

The following table is a summary of the action that should be taken following the results of this report. An 'x' marked in the cell indicates the issue and if a problem was found. Cell shading has been applied to assist understanding. Green requires no action, yellow is for indicative or investigative purposes only and red requires remedial action:

1. **Not applicable no faults found:** The inspection resulted in no faults being found for this problem type
2. **No Action:** No remedial action is required
3. **Fault found no action, information purposes only:** Fault found but the significance is minimal or consequences to living/building conditions are deemed insignificant
4. **Repair all faults found:** All faults listed to be investigated to discover/confirm the root cause of the thermal anomaly and then repaired.

Suspected Fault	Not Applicable, no faults found	No Action	Fault found, for information purposes or for further investigation	Investigate and repair all faults found
Insulation Continuity			x	
Energy loss through window panes				
Air Leakage				x
Thermal/Cold Bridging	x			
Damp	x			
Delamination	x			
(Other Problems)	x			



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Energy savings

The following table indicates how energy savings could be established for this inspection. **Initial visual inspection must be undertaken to confirm or determine the root cause of the overall suspected visual problem:**

Fault	Possible Remedial Action	Effect of Energy Performance	Applicable to this inspection
Insulation Continuity:- Excess energy is being lost through the building fabric/envelope due to missing or defective insulation	Either add additional insulation to the area if found to be missing. Old or damaged insulation may require repair or replacement depending on economic assessment showing the most cost efficient and effective form of action	Reduction in thermal transfer through the building envelope. This will require less energy to heat the property reducing CO ² output, KwHr of energy used and a cost saving per year	Yes Faults found but the area was left open for a week and the problem will cease once the area is checked and found to be fully sealed and dry
Energy loss through window panes:- Excess energy is being lost through the window panes themselves	Assessment must be carried out to determine if the windows can be adjusted to incorporate double/triple glazing from internal or external perspectives or of a complete replacement is required	Reduction in thermal transfer through the window panes. This will require less energy to heat the property reducing CO ² output, KwHr of energy used and a cost saving per year	No
Air Leakage:- Path of air leakage is found through the building envelope causing excess energy to be lost or drafts internally	Seals should be assessed for their integrity and then either repaired, replaced or added if they are found to be not present. Any damage found should be repaired accordingly or parts replaced if found to be defective or beyond repair	Heat will be kept within the building envelope and drafts will be reduced allowing for better internal conditions. This will require less energy to heat the property reducing CO ² output, KwHr of energy used and a cost saving per year	Yes



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



<p>Thermal/Cold Bridging:- Path of cold/thermal transfer through the building envelope at an unacceptable temperature differentials which could lead to other problems involving condensation and damp</p>	<p>The path of the cold or thermal bridge needs to be assessed in order to determine the correct course of remedial action. This could include increasing or improving insulation in this area or the detail itself may benefit from a redesign or replacement if found to be defective</p>	<p>Reduction in thermal transfer through the building envelope. This will require less energy to heat the property reducing CO² output, KwHr of energy used and a cost saving per year. Additionally associated problems such as condensation and damp which can lead to mould growth will be avoided</p>	<p>No</p>
<p>Damp:- Wet areas of the building envelope or insulation</p>	<p>Root cause of the damp needs to be ascertained first. This will determine if it is due to condensation or water ingress from an envelope penetration or system water. A chlorine test will assist as system water will be chlorinated. If there is a penetration this area must be sealed or the water leak stopped. If condensation is found then dew point has been reached so surface temperature must be raised either through the addition of insulation or a redesign or replacement of the part where condensation is forming.</p>	<p>Damp insulation is not as effective in the reduction of thermal transfer so if the area of damp is effectively fixed less energy will be required to heat the property reducing CO² output, KwHr of energy used and a cost saving per year. Additionally associated problems such as mould growth will be avoided allowing for a healthier living environment</p>	<p>No</p>
<p>Delamination:- Insulation panelling begins to become unstuck or apart</p>	<p>Assessment is required to determine of the panels can be repaired or if they need to be replaced</p>	<p>Reduction in thermal transfer through the building envelope. This will require less energy to heat the property reducing CO² output, KwHr of energy used and a cost saving per year</p>	<p>No</p>



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Explanation of fault severity

Each of the Visual Documentation problems identified in the proceeding pages has been assigned a fault severity rating. We have arrived at this rating using the following table. Our reference point is either the TCso or TCsi depending on if the area was inspected from an internal or external perspective. An external inspection would utilise TCso and an internal inspection would utilise TCsi:

Fault Ratings	Minor (4)	Important (3)	Serious (2)	Critical (1)
Temp above TCso/TCsi	0-2	2-4	4-8	8+

Important Note:

The proceeding pages will now summarise and document in full the findings for this inspection. Please note that Ti Thermal Imaging locate the areas of excessive thermal anomaly and we offer suggestions to the root cause and possible remedial action only based on our experience. Ti cannot accept responsibility for the actual root cause of the anomaly and remedial action should be based on further visual inspection by the appropriate agent.



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87






Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Inventory of Image Capture shown by Baseline Page Number:



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Webmanager tutorial snapshot:

Login to Webmanager at the following locations using your username and password:

<http://193.228.155.40/inspectrend> or www.thermalimaging.co.uk

Navigate to the area you need using one of the 6 tabs at the top of the screen:

Overview	Inspection	Inventory	Problems	Cost Benefit	Baseline Trending
Summary listing all problems active or closed with severity grade.	Select site and then hit search to reveal historical list of inspections. Select more next to the inspection that you want to see further details of. At the bottom of the page is a "Reports" button. Hit this to display your reports. The complete report will be the very first one and will be prefixed by "1_" in order for it to be located at the very top of the list.	Select site and then hit search to reveal a full inventory of surveyed areas, test status, priority to site operation and last inspected date.	Select site and then hit search to reveal a list of all open/closed problems found with severity grade, repair status and date found. Attach a work order here for remedial action and view the problem in its own individual report page.	Select site and then hit search to reveal the quantified results if you have exercised this option. Note: This is not enabled for all inspections	Select site and then hit search to reveal baseline trend data for all areas surveyed. Here you can view individual trend reports for each area where the latest IR/DC images are displayed with a historical temperature graph for baseline temp/current insp. Temp and threshold temp.



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Cover Page for Visual Executive and Operations summary of problems found

**Also available on your Webmanager Overview page
Please use your login details provided**

<http://193.228.155.40/inspectrend>



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





INFRARED THERMOGRAPHIC INSPECTION
OF
VISUAL PROBLEMS

Provided for

Report Date: 23/04/2012

Overview:

The Infrared Inspection was performed by TI Thermal Imaging, by a certified infrared Thermographer. All of the items inspected are listed in this InspecTrend report. Any anomalies are listed in order of priority based on the component's temperature rise, as measured from a reference component of equal type and load at the time of the inspection. TI Thermal Imaging assumes no liability directly or indirectly as a result of this inspection.

Current Inspection No: 1820 April 23, 2012

Prior Inspection No:

Priority	Temp Rise	Current Inspection	Prior Inspection	Percent of Change
1-Critical		0 = 0%	NA	NA
2-Serious		0 = 0%	NA	NA
3-Important		2 = 33%	NA	NA
4-Minor		4 = 67%	NA	NA
Total Tested Problems:		6	NA	NA
Number of New Documented Problems:		6 = 100%	NA	NA
Number of Tested re-occurring Problems:		0 = 0%	NA	NA

Number of prior problems which were Not Tested this inspection : NA

Number of Total Open Problems : **6**

Number of prior problems which tested Normal this inspection : NA

I hereby certify the above project was inspected by myself or under my direction and that the enclosed data is the direct result of this inspection.

TI Thermal Imaging

Wallace, Richard

Certification Level/No.: ITC Level II

* Summary of reoccurring problems on following page(s)



Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



List of Open Problems

Full list of thermal, mechanical and visual issues found

Also available on your Webmanager Problems page
Please use your login details provided


<http://193.228.155.40/inspectrend>



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





List of All Open Problems

Operation Priority Key

CTO = Critical to operation
 ETO = Essential to operation
 NON = Non-essential to operation
 UNC = Un-Classified

Report Date: 23/04/2012

Prior Inspection No :

Current Inspection No : 1820 April 23, 2012

Prob#	Asset ID		Temp Insp#	Rise	% Load	Severity	Status
V 5	-	Equipment: SIDE ELEVATIONS \ EAST \ NORTH SIDE Component: Elevated temperature at AR1	1820			3-Important	TESTED
V 4	-	Equipment: SIDE ELEVATIONS \ EAST \ SOUTH SIDE Component: Elevated temperature at AR1	1820			3-Important	TESTED
V 6	-	Equipment: SIDE ELEVATIONS \ NORTH \ ACCESS DOOR Component: Elevated temperature at AR1	1820			4-Minor	TESTED
V 3	-	Equipment: SIDE ELEVATIONS \ SOUTH \ ABOVE REAR ACCESS DOOR Component: Elevated temperature at AR1	1820			4-Minor	TESTED
V 2	-	Equipment: SIDE ELEVATIONS \ SOUTH \ EAST Component: Elevated temperature at AR1 and AR2	1820			4-Minor	TESTED
V 1	-	Equipment: SIDE ELEVATIONS \ SOUTH \ WEST Component: Elevated temperature at AR1	1820			4-Minor	TESTED



Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Inspection Inventory Pages

Equipment listing and test status

Also available on your Webmanager Inventory page with Photos
Please use your login details provided

<http://193.228.155.40/inspectrend>



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Current Inspection Inventory Status By Inspection Order

Report Date: 23/04/2012

Inspected By : Wallace, Richard

Prior Inspection No:

Current Inspection No: 1820

Problem Type Key

TD = T/D Electrical
M = Mechanical
V = Visual Inspection

Operation Priority Key

CTO = Critical to operation
ETO = Essential to operation
NON = Non-essential to operation
UNC = Un-Classified

Equipment Test Status Key

TBT = To Be Tested
NT/NL = Not Tested/No Load
NT/TC = Not Tested/Time Constraint
NT/UR = Not Tested/Under Repair
NT/LO = Not Tested/Locked Out
NT/NA = Not Tested/Not Available
NT/NS = Not Tested/Not Specified
NSFI = Not Selected for this insp.

Work Order	Asset ID	Equipment Description	CTO	Tested	Problem #	Test Status Notes
NI	-	ROOF	CTO	TESTED		
NI	-	EAST	CTO	TESTED		
NI	-	WEST	CTO	TESTED		
NI	-	SIDE ELEVATIONS	CTO	TESTED		
NI	-	SOUTH	CTO	TESTED		
NI	-	WEST	CTO	TESTED	V1	
NI	-	CENTRE	CTO	TESTED		
NI	-	EAST	CTO	TESTED	V2	
NI	-	ABOVE REAR ACCESS DOOR	CTO	TESTED	V3	
NI	-	EAST	CTO	TESTED		
NI	-	PLANTROOM	CTO	TESTED		
NI	-	SOUTH SIDE	CTO	TESTED	V4	
NI	-	NORTH SIDE	CTO	TESTED	V5	
NI	-	NORTH	CTO	TESTED		
NI	-	VIEWED FROM EAST	CTO	TESTED		
NI	-	VIEWED FROM WEST	CTO	TESTED		
NI	-	ACCESS DOOR	CTO	TESTED	V6	
NI	-	WEST	CTO	TESTED		
NI	-	NORTH SIDE	CTO	TESTED		
NI	-	SOUTH SIDE	CTO	TESTED		



Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Documentation pages for Visual findings

Details of Visual problems found

Also available on your Webmanager Problems page
Please use your login details provided

<http://193.228.155.40/inspectrend>



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87



Visual Problem Documentation

Work Order#: NOT ISSUED

Location/Equipment Information
Asset ID: - SIDE ELEVATIONS SOUTH WEST

Current Prob No: Visual/1	
Is Chronic:	No
Operation Priority:	Critical to operation
Repair Priority:	4-Minor


InspectionNo: 1820
Report Date: 23/04/2012

Classification: Buildings
 Observations: Elevated temperature at AR1
 What is the Cause: Suspected air leakage
 Recommendations: Check seals and repair or replace where necessary



File: IR_1379A.jpg	Date: 23/04/2012
File: DC_1378.jpg	Date: 23/04/2012

Technician:	Wallace, Richard
-------------	------------------



Visual Problem Documentation

Work Order#: NOT ISSUED

Location/Equipment Information
Asset ID: - SIDE ELEVATIONS SOUTH EAST

Current Prob No: Visual/2	
Is Chronic:	No
Operation Priority:	Critical to operation
Repair Priority:	4-Minor

InspectionNo: 1820
Report Date: 23/04/2012

Classification: Buildings
Observations: Elevated temperature at AR1 and AR2
What is the Cause: Suspected air leakage
Recommendations: Check seals and repair or replace where necessary



File: IR_1383A.jpg	Date: 23/04/2012
File: DC_1384.jpg	Date: 23/04/2012

Technician:	Wallace, Richard
-------------	------------------

Visual Problem Documentation

Work Order#: NOT ISSUED

Location/Equipment Information
Asset ID: - SIDE ELEVATIONS SOUTH ABOVE REAR ACCESS DOOR

Current Prob No: Visual/3	
Is Chronic:	No
Operation Priority:	Critical to operation
Repair Priority:	4-Minor

InspectionNo: 1820
Report Date: 23/04/2012

Classification: Buildings
 Observations: Elevated temperature at AR1
 What is the Cause: Suspected insulation incontinuity
 Recommendations: Repair, add or replace insulation as necessary



File: IR_1385A.jpg	Date: 23/04/2012
File: DC_1386.jpg	Date: 23/04/2012

Technician:	Wallace, Richard
-------------	------------------



Visual Problem Documentation

Work Order#: NOT ISSUED

Location/Equipment Information
Asset ID: -
SIDE ELEVATIONS
EAST
SOUTH SIDE

Current Prob No: Visual/4	
Is Chronic:	No
Operation Priority:	Critical to operation
Repair Priority:	3-Important



InspectionNo: 1820
Report Date: 23/04/2012

Classification: Buildings

Observations: Elevated temperature at AR1

What is the Cause: Insulation suspected of damp due to poor panel seals

Recommendations: Repair or replace panel seals to prevent water ingress



File: IR_1389A.jpg	Date: 23/04/2012
File: DC_1390.jpg	Date: 23/04/2012

Technician:	Wallace, Richard
-------------	------------------

Visual Problem Documentation

Work Order#: NOT ISSUED

Location/Equipment Information
Asset ID: -
SIDE ELEVATIONS
EAST
NORTH SIDE

Current Prob No: Visual/5	
Is Chronic:	No
Operation Priority:	Critical to operation
Repair Priority:	3-Important


InspectionNo: 1820
 Report Date: 23/04/2012

Classification: Buildings

Observations: Elevated temperature at AR1

What is the Cause: Insulation suspected of damp due to poor panel seals

Recommendations: Repair or replace panel seals to prevent water ingress



File: IR_1391A.jpg	Date: 23/04/2012
File: DC_1392.jpg	Date: 23/04/2012

Technician:	Wallace, Richard
-------------	------------------

Visual Problem Documentation


Work Order#: NOT ISSUED

Location/Equipment Information
Asset ID: - SIDE ELEVATIONS NORTH ACCESS DOOR

Current Prob No: Visual/6	
Is Chronic:	No
Operation Priority:	Critical to operation
Repair Priority:	4-Minor

InspectionNo: 1820
Report Date: 23/04/2012

Classification: Buildings
 Observations: Elevated temperature at AR1
 What is the Cause: Suspected air leakage
 Recommendations: Check seals and repair or replace where necessary



File: IR_1399A.jpg	Date: 23/04/2012
File: DC_1400.jpg	Date: 23/04/2012

Technician:	Wallace, Richard
-------------	------------------



Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Benchmark Baseline Trending

**Full list of equipment baseline trends is also available on your Webmanager
Please use your login details provided**

<http://193.228.155.40/inspectrend>



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87





Equipment Baseline Trending Report By Inspection Order

Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

ROOF \ EAST

Equipment ID: -


Work Order: NI



IR_1405.jpg




DC_1406.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	4 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

ROOF \ WEST

Equipment ID: -


Work Order: NI



IR_1407.jpg



DC_1408.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	4 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ SOUTH \ WEST

Equipment ID: -


Work Order: NI



IR_1379.jpg



DC_1380.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	9 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging

ritten consent.

Equipment Baseline Trending Report By Inspection Order

Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ SOUTH \ CENTRE

Equipment ID: -


Work Order: NI



IR_1381.jpg



DC_1382.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	6 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ SOUTH \ EAST

Equipment ID: -


Work Order: NI



IR_1383.jpg



DC_1384.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	6 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging

ritten consent.



Equipment Baseline Trending Report By Inspection Order


Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ SOUTH \ ABOVE REAR ACCESS DOOR

Equipment ID: -


Work Order: NI



IR_1385.jpg



DC_1386.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	8 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ EAST \ PLANTROOM

Equipment ID: -


Work Order: NI



IR_1387.jpg



DC_1388.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	5 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging

ritten consent.



Equipment Baseline Trending Report By Inspection Order


Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ EAST \ SOUTH SIDE

Equipment ID: -


Work Order: NI



IR_1389.jpg



DC_1390.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	11 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order


Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ EAST \ NORTH SIDE

Equipment ID: -


Work Order: NI



IR_1391.jpg



DC_1392.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	10 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging

ritten consent.

Equipment Baseline Trending Report By Inspection Order


Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ NORTH \ VIEWED FROM EAST

Equipment ID: -


Work Order: NI



IR_1393.jpg



DC_1394.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	6 C	7 C	6 C		



Equipment Baseline Trending Report By Inspection Order


Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ NORTH \ VIEWED FROM WEST

Equipment ID: -


Work Order: NI



IR_1395.jpg



DC_1396.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	6 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order


Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ NORTH \ ACCESS DOOR

Equipment ID: -


Work Order: NI



IR_1399.jpg



DC_1400.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	8 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging

ritten consent.



Equipment Baseline Trending Report By Inspection Order

Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ WEST \ NORTH SIDE

Equipment ID: -


Work Order: NI



IR_1401.jpg



DC_1402.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	6 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

Current Inspection No: 1820 April 23, 2012

Report Date: 23/04/2012

SIDE ELEVATIONS \ WEST \ SOUTH SIDE

Equipment ID: -


Work Order: NI



IR_1403.jpg



DC_1404.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1820	23/04/2012	TESTED	6 C	7 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Work Order Documentation pages Fax or Email back Corrective Work Orders

Also available on your Webmanager Problems page
Please use your login details provided

<http://193.228.155.40/inspectrend>



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87



Documentation/ Work Order

Visual: Please add Corrective Work Order

Work Order #: NOT ISSUED

Corrective Work Order #:

PLEASE ADD CORRECTIVE WORK ORDERS ABOVE

InspectionNo: 1820
Report Date: 23/04/2012

1820-1 Current Prob No: Visual/1

Location/Equipment Information	
Asset ID:	-
Barcode:	NI
Location:	SIDE ELEVATIONS SOUTH WEST

Repair Priority:	4-Minor
Hazard Type:	Visual
Hazard Classification:	Buildings
Hazard Group:	Elevated temperature
Hazard Issue:	at AR1
Observations:	Elevated temperature at AR1
What is the Cause:	Suspected air leakage



Photo File: IR_1379A.jpg

Photo Date: 23/04/2012

Photo File: DC_1378.jpg

Photo Date: 23/04/2012

Repair Information		Loss to Production	
<p>PLEASE FAX BACK AFTER REPAIR TO: 0871 900 4978 OR INFO@THERMALIMAGING.CO.UK</p>		<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown	
		Consequences of Failure: <input type="text"/> Parts Req. Before Failure: <input type="text"/> Parts Req. After Failure: <input type="text"/> Repair Recommendation: <input type="text"/>	Repair Date: <input type="text"/> Repaired By: <input type="text"/> Root Cause: <input type="text"/> Repair Procedure: <input type="text"/>
<input type="text"/>		Repair Notes: <input type="text"/>	
<input type="text"/>		<input type="text"/>	

Documentation/ Work Order Visual: Please add Corrective Work Order

Work Order #: NOT ISSUED

Corrective Work Order #:

PLEASE ADD CORRECTIVE WORK ORDERS ABOVE

InspectionNo: 1820
Report Date: 23/04/2012

1820-2 Current Prob No: Visual/2

Location/Equipment Information	
Asset ID:	-
Barcode:	NI
Location:	SIDE ELEVATIONS SOUTH EAST

Repair Priority:	4-Minor
Hazard Type:	Visual
Hazard Classification:	Buildings
Hazard Group:	Elevated temperature
Hazard Issue:	at AR1 and AR2
Observations:	Elevated temperature at AR1 and AR2
What is the Cause:	Suspected air leakage



Photo File: IR_1383A.jpg

Photo Date: 23/04/2012

Photo File: DC_1384.jpg

Photo Date: 23/04/2012

Repair Information		Loss to Production	
<p>PLEASE FAX BACK AFTER REPAIR TO: 0871 900 4978 OR INFO@THERMALIMAGING.CO.UK</p>		<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown	
		Consequences of Failure: <input type="text"/>	Repair Date: <input type="text"/>
Parts Req. Before Failure: <input type="text"/>	Root Cause: <input type="text"/>	Repair Procedure: Check seals and repair or replace where necessary	
Parts Req. After Failure: <input type="text"/>	Repair Notes: <input type="text"/>		
Repair Recommendation: <input type="text"/>			

Documentation/ Work Order

Visual: Please add Corrective Work Order

Work Order #: NOT ISSUED

Corrective Work Order #:

PLEASE ADD CORRECTIVE WORK ORDERS ABOVE

InspectionNo: 1820
Report Date: 23/04/2012

1820-3 Current Prob No: Visual/3

Location/Equipment Information	
Asset ID:	-
Barcode:	NI
Location:	SIDE ELEVATIONS SOUTH ABOVE REAR ACCESS DOOR

Repair Priority:	4-Minor
Hazard Type:	Visual
Hazard Classification:	Buildings
Hazard Group:	Elevated temperature
Hazard Issue:	at AR1
Observations:	Elevated temperature at AR1
What is the Cause:	Suspected insulation incontinuity





Photo File: IR_1385A.jpg

Photo Date: 23/04/2012

Photo File: DC_1386.jpg

Photo Date: 23/04/2012

Repair Information		Loss to Production	
<p>PLEASE FAX BACK AFTER REPAIR TO: 0871 900 4978 OR INFO@THERMALIMAGING.CO.UK</p>		<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown	
		Consequences of Failure: <input type="text"/> _____ _____	Repair Date: <input type="text"/>
Parts Req. Before Failure: <input type="text"/> _____ _____	Root Cause: <input type="text"/> _____ _____	Repair Procedure: Check seals and insulation and repair or replace where necessary	
Parts Req. After Failure: <input type="text"/> _____ _____	Repair Notes: <input type="text"/> _____ _____		
Repair Recommendation: Repair, add or replace insulation as necessary			

Documentation/ Work Order

Visual: Please add Corrective Work Order

Work Order #: NOT ISSUED

Corrective Work Order #:

PLEASE ADD CORRECTIVE WORK ORDERS ABOVE

InspectionNo: 1820
Report Date: 23/04/2012

1820-4 Current Prob No: Visual/4

Location/Equipment Information	
Asset ID:	-
Barcode:	NI
Location:	SIDE ELEVATIONS EAST SOUTH SIDE

Repair Priority:	3-Important
Hazard Type:	Visual
Hazard Classification:	Buildings
Hazard Group:	Elevated temperature
Hazard Issue:	at AR1
Observations:	Elevated temperature at AR1
What is the Cause:	Insulation suspected of damp due to poor panel seals




Photo File: IR_1389A.jpg

Photo Date: 23/04/2012

Photo File: DC_1390.jpg

Photo Date: 23/04/2012

Repair Information		Loss to Production	
<p>PLEASE FAX BACK AFTER REPAIR TO: 0871 900 4978 OR INFO@THERMALIMAGING.CO.UK</p>		<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown	
		Consequences of Failure: <input type="text"/> _____ _____	Repair Date: <input type="text"/>
Parts Req. Before Failure: <input type="text"/> _____ _____	Root Cause: <input type="text"/> _____ _____	Repair Procedure: <input type="text"/> _____ _____	
Parts Req. After Failure: <input type="text"/> _____ _____	Repair Notes: <input type="text"/> _____ _____	_____ _____	
Repair Recommendation: <input type="text"/> Repair or replace panel seals to prevent water ingress _____ _____			

Documentation/ Work Order

Visual: Please add Corrective Work Order

Work Order #: NOT ISSUED

Corrective Work Order #:

PLEASE ADD CORRECTIVE WORK ORDERS ABOVE

InspectionNo: 1820
Report Date: 23/04/2012

1820-5 Current Prob No: Visual/5

Location/Equipment Information	
Asset ID:	-
Barcode:	NI
Location:	SIDE ELEVATIONS EAST NORTH SIDE

Repair Priority:	3-Important
Hazard Type:	Visual
Hazard Classification:	Buildings
Hazard Group:	Elevated temperature
Hazard Issue:	at AR1
Observations:	Elevated temperature at AR1
What is the Cause:	Insulation suspected of damp due to poor panel seals





Photo File: IR_1391A.jpg

Photo Date: 23/04/2012

Photo File: DC_1392.jpg

Photo Date: 23/04/2012

Repair Information		Loss to Production	
<p>PLEASE FAX BACK AFTER REPAIR TO: 0871 900 4978 OR INFO@THERMALIMAGING.CO.UK</p>		<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown	
		Consequences of Failure: <input type="text"/>	Repair Date: <input type="text"/>
Parts Req. Before Failure: <input type="text"/>	Root Cause: <input type="text"/>	<input type="text"/>	
Parts Req. After Failure: <input type="text"/>	Repair Procedure: <input type="text"/>		
Repair Recommendation: <input type="text"/>	Repair Notes: <input type="text"/>	<input type="text"/>	

Documentation/ Work Order

Visual: Please add Corrective Work Order

Work Order #: NOT ISSUED

Corrective Work Order #:

PLEASE ADD CORRECTIVE WORK ORDERS ABOVE

InspectionNo: 1820
Report Date: 23/04/2012

1820-6 Current Prob No: Visual/6

Location/Equipment Information	
Asset ID:	-
Barcode:	NI
Location:	SIDE ELEVATIONS NORTH ACCESS DOOR

Repair Priority:	4-Minor
Hazard Type:	Visual
Hazard Classification:	Buildings
Hazard Group:	Elevated temperature
Hazard Issue:	at AR1
Observations:	Elevated temperature at AR1
What is the Cause:	Suspected air leakage




Photo File: IR_1399A.jpg

Photo Date: 23/04/2012

Photo File: DC_1400.jpg

Photo Date: 23/04/2012

Repair Information		Loss to Production	
<p>PLEASE FAX BACK AFTER REPAIR TO: 0871 900 4978 OR INFO@THERMALIMAGING.CO.UK</p>		<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown	
		Consequences of Failure: <input type="text"/> _____ _____	Repair Date: <input type="text"/>
Parts Req. Before Failure: <input type="text"/> _____ _____	Root Cause: <input type="text"/> _____ _____	Repair Procedure: Check seals and repair or replace where necessary	
Parts Req. After Failure: <input type="text"/> _____ _____	Repair Notes: <input type="text"/> _____ _____	Repair Recommendation: Check seals and repair or replace where necessary	



Ti Thermal Imaging LTD

Unit 8, Weybridge Business Centre, 66 York Road, Weybridge, Surrey, KT13 9DY

Tel: 0845 458 6315 Fax: 0871 9004978 E-mail: info@thermalimaging.co.uk Web: www.thermalimaging.co.uk



Client Work Appraisal

We are continually trying to improve our service and ensure that all our inspections are carried out to the highest standards. Please use the form below to add your comments, anonymously if you prefer and send back to us at the address above or:

Email: info@thermalimaging.co.uk

Fax: +44 870 9004971

Ti Job Number: (Optional)	Excellent	Good	Mediocre	Poor	Comments
Office:					
Response time to enquiry					
Content of information sent on enquiry					
Telephone and email manner					
Price					
Value					
Engineer:					
Time keeping					
Appearance					
Code of conduct					
Subject knowledge					
Method of work					
Engineer flexibility					
Inspection Specification:					
Equipment and software					
Report content					
Report delivery time					
Report retrieval					
Other Comments:					



Report generated by Ti Thermal Imaging LTD.

Company Registered in England: 04450573 VAT No. 828 6288 87

