

Stroma Technology Ltd

Bolton Council - Westhoughton Area Office Market Street, Westhoughton,

InspectionNo: 1626 Report Date: 15/01/2012

Classification:

Observations:

What is the Cause:

Recommendations:

Visual Problem Documentation

Location/Equipment Information

Asset ID: -

EXTERNAL ELEVATIONS

LINK

BOLTON ROAD

Work Order#: **NOT ISSUED**

Current Prob No: Visual/4

Is Chronic: No

Operation Priority: Critical to operation

Repair Priority:

1-Critical


Page 4


Buildings

Elevated surface temperature at AR1 and AR2

Poor insulating properties leading to excess energy loss and other associated problems

Improve glazing for better insulating effect





File: IR_0831A.jpg File: DC_0832.jpg Date: 19/10/2011 Date: 19/10/2011

Technician:

James, Humphries