


Stroma Technology Ltd
 Morris Homes - 217 London Road
 217 London Road,

InspectionNo: 2051
 Report Date: 15/03/2013

Classification: Buildings
 Observations: Decreased temperature at AR1
 What is the Cause: Suspected air leakage
 Recommendations: Check seals and repair or replace where necessary

Location/Equipment Information
Asset ID: - INTERNAL ELEVATIONS GROUND FLOOR REAR ROOM

Current Prob No: Visual/3	
Is Chronic:	No
Operation Priority:	Critical to operation
Repair Priority:	1-Critical



File: IR_1781A.jpg	Date: 15/03/2013	Time: 01:37 PM
File: DC_1782.jpg	Date: 15/03/2013	Time: 07:31 AM

Technician:	Wallace, Richard
Certification Level/No.:	ITC Level II