

Single Image Thermographic Inspection Report

TI Site 91 Single Elevation Building Inspection

Current Inspection No: 1656

November 15, 2011

Report Date: 15/11/2011

House ID: 36 THAMES MEADOW



IR_34695.jpg



DC_34696.jpg


Inspection History:

Inspection No	Date Inspected	Measured Temp	Ambient Temp	Status Note
1656	15/11/2011	16 C	6C	

Customer Notes

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging

ritten consent.



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.37

Equipment ID: 37 THAMES MEADOW

Work Order: NI

Key
CTO = Critical to operation
ETO = Essential to operation
NON = Non-essential to operation
UNC = Un-Classified
NI = Not Issued


Operation Priority: CTO



IR_34697.jpg




DC_34698.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	29 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.38


Equipment ID: 38 THAMES MEADOW

Work Order: NI

Key

- CTO = Critical to operation
- ETO = Essential to operation
- NON = Non-essential to operation
- UNC = Un-Classified
- NI = Not Issued


Operation Priority: CTO



IR_34699.jpg




DC_34700.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	9 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.39

Equipment ID: 39 THAMES MEADOW

Work Order: NI

Key

- CTO = Critical to operation
- ETO = Essential to operation
- NON = Non-essential to operation
- UNC = Un-Classified
- NI = Not Issued


Operation Priority: CTO



IR_34701.jpg




DC_34702.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	10 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.40

Equipment ID: 40 THAMES MEADOW

Work Order: NI

Key

- CTO = Critical to operation
- ETO = Essential to operation
- NON = Non-essential to operation
- UNC = Un-Classified
- NI = Not Issued


Operation Priority: CTO



IR_34703.jpg




DC_34704.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	8 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.41

Equipment ID: 41 THAMES MEADOW

Work Order: NI

Key

- CTO = Critical to operation
- ETO = Essential to operation
- NON = Non-essential to operation
- UNC = Un-Classified
- NI = Not Issued


Operation Priority: CTO



IR_34705.jpg




DC_34706.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	17 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.42


Equipment ID: 42 THAMES MEADOW

Work Order: NI

Key

- CTO = Critical to operation
- ETO = Essential to operation
- NON = Non-essential to operation
- UNC = Un-Classified
- NI = Not Issued


Operation Priority: CTO



IR_34707.jpg




DC_34708.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	13 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.43

Equipment ID: 43 THAMES MEADOW

Work Order: NI

Key
CTO = Critical to operation
ETO = Essential to operation
NON = Non-essential to operation
UNC = Un-Classified
NI = Not Issued


Operation Priority: CTO



IR_34709.jpg




DC_34710.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	9 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.44


Equipment ID: 44 THAMES MEADOW

Work Order: NI

Key

- CTO = Critical to operation
- ETO = Essential to operation
- NON = Non-essential to operation
- UNC = Un-Classified
- NI = Not Issued


Operation Priority: CTO



IR_34711.jpg




DC_34712.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	11 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging



Equipment Baseline Trending Report By Inspection Order

TI
TI Site 91 Single Elevation Building Inspection

Prior Inspection No:
Current Inspection No: 1656 November 15, 2011

Report Date: 15/11/2011

NO.45

Equipment ID: 45 THAMES MEADOW

Work Order: NI

Key
CTO = Critical to operation
ETO = Essential to operation
NON = Non-essential to operation
UNC = Un-Classified
NI = Not Issued


Operation Priority: CTO



IR_34713.jpg



DC_34714.jpg



Inspection History:

Inspection No	Date Inspected	Test Status	Measured Temp	Threshold Temp	Ambient Temp	Status Note	Customer Notes
1656	15/11/2011	TESTED	11 C	30 C	6 C		

This report was generated by InspecTrend and this inspection was performed by: TI Thermal Imaging